




Honda Motor replaces Mobile DTE 25 hydraulic oil in crushion bearing every 200 hours due to oil oxidation from overheated bearing. Honda installed MB-50 dedicated oil purifier to continuously remove excessive particulate and oil oxidation since 2003.

Hydraulic oil is kept continuously clean like new oil to reduce hydraulic failures. OilPure extends the oil life as Honda has not changed the oil since its first installation.



Honda is a registered trademark of Honda Motor Company.